



Remove the 2 screws below
the metal housing and slide
the unit down to release



Remove the 6
screws from the
backing plate to
access wiring




**Disconnect all
cables from
OEM controller
and remove
the 4 screws
holding it into
the housing**




Install the 2 dog-
bone brackets
using the button
head screw
provided



Reattach the backing plate to the housing and pass all OEM cables back through it (you can route ambient probe through here as well) then reattach the housing to the front of the hopper



Connect the red/
black cable to the
LSMC mount





Install the front plate
using the 4
countersunk screws
provided

Connect drive
cable to mount
and FB and you
are good to go!



If you didn't order a cable you will require a
male to male 5.5x2.5mm barrel connector
cable